

SERVICE INSTRUCTION 04/11

Publication Ref. Number: 101

Date: 01/Aug/2011

SUBJECT

Stubai 3000kg karabiner marking

CATEGORY

Advisory

APPLICABILITY

Ultramagic envelopes and baskets manufactured between June and July 2011

NOTE: N-500 envelopes and C-14 baskets excluded

COMPLIANCE

None (Informative only)

BACKGROUND

Stubai has reported about a series of karabiners delivered with a typographical mistake in the marking which could lead to confusion: On the side of the Stubai logo, model nr. '3400' is engraved instead of '3000'. Other markings are correct.

However, normal strength of the karabiners is warranted.

INSTRUCTIONS

Affected karabiners can continue to be used. However, Ultramagic offers replacement at no extra charge for all the units affected.

Contact your dealer or the factory for the replacement or any question.



DOA Head – Aeronautical Engineer

The content of this document has been approved under the privilege of the Design Organisation Approval nr.
EASA.21J.351

Ultramagic, S.A.

Aeròdrom **Gral. Vives** Igualada-Òdena
Ap. Correus (P.O. Box): 171 – 08700 Igualada (BCN) Spain
Tel.: +34 93 804 22 02 – Fax: +34 93 803 56 04
e-mail: admin@ultramagic.com