Globos Balloons Montgolfières Heissluftballone Montgolfiera Balónu Ballonger Kuumailmapallot Balões Ballons Аэростаты Globus 熱気球

Page 1 of 2

SERVICE BULLETIN 1/99

Date	•	
Daw	٠	

26-08-99

Subject:

Fisher M220M valve replacement in cylinders.

Category:

Mandatory.

Serial number tanks affected:

M-20 from 236 to 262 with Fisher connection. M-30 from 334 to 415 with Fisher connection.

Fisher M220M connector is similar to REGO 7141M and can be recognised easily as having the inner ripple in black.

Reason:

It has been proved that in some very special cases (we believe that refuelling with high pressure trucks) Fisher M220M inner part can be disassembled by itself. This parts (ring, spring, etc.) can get in the cylinder or be blocking the 1/4 main valve.

For this reason the Fisher M220M must be replaced for the Rego 7141M inmediately.



Globos Balloons Montgolfières Heissluftballone Montgolfiera Balónu Ballonger Kuumailmapallot Balões Ballons Аэростаты Globus 熱 気球

Page 2 of 2

Compliance:

No flight or tank manipulation is allowed in the meantime except for replacing the piece. No disconnection of burner can be made unless valve tank is completely closed without forcing it.

Instructions:

Contact your dealer or directly the factory to replace the Fisher M220M valves.